



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor

Kathleen Clarke
Executive Director

Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

June 14, 1999

CERTIFIED RETURN RECEIPT
P 074 976 694

Darin Olson
ECDC Environmental L.C.
1111 West Highway 123
P.O. Box 69
East Carbon, Utah 84520

Re: Updated Permit Information Needed, ECDC Environmental L.C., ECDC Clay Mine, M/015/062,
Emery County, Utah

Dear Mr. Olson:

A recent staff review of the ECDC Clay Mine files identified several items within the original approved permit application which need to be updated or clarified. These items are:


- The present delineation of areas to be mined is a generalized outline of the proposed site. Please provide a scaled map showing the current surface facilities/disturbances to our office by July 28th.
- A reclamation treatments map was requested in the April 1993 Division review of the ECDC notice. Due to an oversight, this map was never provided or mentioned in later Division correspondence. Please provide a scaled reclamation treatments map showing the currently approved reclamation treatments for the mine site. Use of the same scale as the surface facilities map is preferred. Please provide this reclamation treatments map to our office within the next 90 days (September 13th). All reclamation treatments should be indicated on this map. For example, if some areas are to receive topsoil while others are not, this should be indicated by different color coding or cross hatching on the map. Also, road reclamation may require deep ripping (>24 inches), while other compacted areas will require shallower scarification/ripping (6-12 inches).
- The 1998 annual report stated that the area of disturbance was "same as 1996." The annual report for 1996 stated "did not know." The report for the year 1997 indicated a total of 20-25 acres. The ECDC bond for this area is presently calculated for a total disturbance of 18 acres. If the site has been (or will be) expanded beyond the 18 acre bonded amount, a

Page 2
Darin Olson
M/015/062
June 14, 1999

recalculation of the reclamation bond amount will be necessary along with the completion of a permit revision form. Please describe the current amount of surface disturbance to clarify this discrepancy.

Your immediate attention to these matters is greatly appreciated. If you have questions or concerns in this regard, please contact me, Doug Jensen or Tony Gallegos of my staff at (801) 538-5286, 538-5382 and 538-5267 respectively.

Sincerely,

A handwritten signature in cursive script, appearing to read "Anthony A. Gallegos". Below the main signature is a smaller, less legible handwritten mark.

D. Wayne Hedberg
Permit Supervisor
Minerals Regulatory Program

cc: Tony Gallegos, DOGM
Doug Jensen, DOGM
M15-62.LTR